

We aim to Repair and Return your radios within 5-10 working days. In some instances this may take longer than estimated, in such cases you will be notified accordingly.

If you require we can collect your radios for an additional **£15.00** which would be added to the final invoice total.

Prices below include labour, spare parts (excluding batteries) and delivery back to the customer.

Please note that we cannot undertake any repairs without a purchase order number.

£95 Digital Radios

including Motorola: DP1400, DP2400, DP2600, DP3441 DP3400, DP3600, DP4400, DP4600, DP4800, SL4000

£69 Licensed Radios

including Motorola: GP320, GP340, GP344, GP388, CP040
Kenwood: TK2202/3202, TK2302/3302, TK2160/3160, TK2360/3360, TK2000/3000
Icom: IC-F15, IC-F25, IC-F51, IC-F61, IC-F3002/4002, IC-F34/44
Vertex: VX351, VX231

£59 Unlicensed Radios

including Motorola: XTNi, XTNiD, XT420, XT460
Kenwood: TK3101, TK3201, TK3301
Icom: IC-F24SR, IC-F27SR
Vertex: VX351 PMR-446, VX241 PMR-446

If your radios require rehousing the costs are:

Digital radios - **£20.00** Licensed radios - **£15.00**

We also repair HYT and Entel radios however we do have to quote before any work is carried out as prices may vary. This also applies for Atex Radios.

If your radio is not listed above then please contact us on **01245 403520**.

Please send your radios in along with our Repair Returns Form to us at:

FAO: Service Department
Brentwood Communications Ltd
BC House
East Hanningfield Road
Chelmsford
Essex
CM3 8EW

